


DIMP – ONGOING COMPLIANCE

Gus Chapman

Manager, Distribution Engineering Services

SCANA Corporation



- 362,000 customers
- 9,072 miles of main
- Approximately 450 miles of transmission
- Provides electric and gas services

SCE&G Gas Divisions

ELEMENTS OF A DIM PLAN

- Knowledge
 - Identify Threats
 - Rank Risks
 - Identify and Implement Mitigation Measures
 - Measure Performance
 - Periodic Evaluation and Improvement
 - Report Results
- 
- A series of three parallel white diagonal lines in the bottom right corner of the slide, extending from the bottom edge towards the right edge.

Know Your System!

GAS SERVICE RECORD

ADDRESS 5090 - Hillside - R.D.

NAME E DATE INSTALLED 3-8-95

CITY or TOWN Colo. SUBDIVISION N/A

SERVICE W.O. NO. _____ PIPE SIZE & KIND 3/4" plastic

PRESSURE: M.P. ☒ H.P. ☐ L.P. ☐ SIZE" of TAP 1/2"

LENGTH MAIN TO CURB VALVE _____ FT. _____ IN.

LENGTH CURB VALVE TO PROPERTY LINE _____ FT. _____ IN.

LENGTH MAIN TO PROPERTY LINE 10 FT. _____ IN.

LENGTH PROPERTY LINE TO METER 90 FT. _____ IN.


SIZE & TYPE of MAIN 2" plastic DEPTH of MAIN 3-FT.

TESTED WITH AIR TO 100 psig FOR 15 MINUTES

INSTALLED BY: Contractor UTILITY SERVICES Foreman TOE MORRIS

REMARKS:

FORM 235 (5-71)







WHAT IS A RISK?

COMMON THREATS


- Excavation Damage
 - Material Failure – Vintage Plastics
 - Vehicle Damage
 - Incorrect Operations – Sewer Cross Bores
 - Natural Forces
- 
- A series of three parallel white diagonal lines in the bottom right corner of the slide, extending from the bottom edge towards the right edge.



EXCAVATION DAMAGE – EXCAVATOR “AT FAULT”



EXCAVATION DAMAGE – OPERATOR “AT FAULT”



MATERIAL FAILURE



VEHICLE DAMAGE



INCORRECT OPERATIONS




NATURAL FORCES

DATA ENTRY ERRORS




EDUCATION



TRAINING



REMINDERS



FIELD EMPLOYEE DEVELOPMENT



PERIODIC REVIEW AND IMPROVEMENT

QUESTIONS?

